

Statement of confirmation

We acknowledge receipt of your notification concerning Safety Gate alert SR/01784/26 issued by Sweden, which identifies an electric shock hazard for electric balloon pump

After full technical comparison and internal inspection of our item GHT-73005, we formally confirm the following:

1. The product in Safety Gate alert SR/01784/26 is not manufactured by our company, our products are with some difference,(Please see attachment)
2. Our GHT-73005 adopts a fully different power switch structural design compared with the defective notified product.
3. The on/off button is locked with anti-drop buckle structure, which cannot fall off or shift under normal use, vibration or slight pulling.
4. Even if external force is applied to the button, there is an isolation barrier between the button and internal live conductive parts, preventing users from touching live components.
5. The electric shock hazard described in alert SR/01784/26 does NOT exist on our GHT-73005, and our product fully meets all protection requirements of components.

All batches of GHT-73005 supplied to your company are safe and compliant for EU market sale.

Factory Signature & Company Stamp: _____

Date: July 30, 2026



SR/01784/26



1. The side edges have contours
2. Handle is different
3. Use the sticker
4. there is no balloon knotter

GHT-73005



1. Our side edges are rounded
2. Handle is different.
3. Our warning content is printed by laser machine, we nevery use sticker
4. Our products is with the balloon knotter



Conclusion: Although it looks similar on the surface, the details are different. This is not the same set of molds, but a replica from Yiwu